

传感器和扭矩扳手的对应表

(根据DIN EN ISO 6789 : 2003标定)

达威力推荐：

+++非常适合 ++很适合 +适合

售后代码	HRC-C2-020	HRC-C2-100	HRC-C2-200	HRC-C2-400	HRC-C2-1100
HCW-18-100		+++			
HCW-18-200			+++		
HCW-18-400				+++	
HCW-18-650					+++
HCW-12-020	+++				
HCW-12-050		+++			
HCW-12-100		+++	++		
HCW-12-120			+++		
HCW-12-200			+++	++	
HCW-12-400				+++	
HCW-12-650					+++
HCW-12-180i	+++				
HCW-12-450i		+++			
HCW-12-900i		+++	++		
HCW-12-1800i			+++	++	
HCW-12-300f				+++	
HCW-11-020	+++	++	+		
HCW-11-040		+++	++	+	
HCW-11-175i	+++	++	+		
HCW-11-350i		+++	++	+	
HCW-11-050		+++	++		
HCW-11-100		+++	++	+	
HCW-11-130			+++	++	+
HCW-11-200			+++	++	+
HCW-11-400				+++	++
HCW-11-650					+++

售后代码	HRC-C2-020	HRC-C2-100	HRC-C2-200	HRC-C2-400	HRC-C2-1100	HRC-C2-3000
HCW-11-050a		+++	++			
HCW-11-100a		+++	++	+		
HCW-11-130a			+++	++	+	
HCW-11-200a			+++	++	+	
HCW-11-800					+++	+
HCW-14-800					+++	+
HCW-15-050		+++	++			
HCW-15-150			+++	++	+	
HCW-15-300				+++	++	
HCW-16-800					+++	+
HCW-16-1000					+++	+
HCW-22-012	+++					
HCW-21-040		+++	++			
HCW-21-100		+++	++	+		
HCW-21-200			+++	++	+	
HCW-21-300				+++	++	
HCW-23-400				+++	++	
HCW-23-800					+++	+
HCW-24-800					+++	+
HCW-25-015	+++	++				
HCW-31-060		+++				
HCW-31-200			+++			
HCW-31-400				+++		
HCW-32-060		+++				
HCW-32-200			+++			
HCW-32-400				+++		